



PAINT INSERTION




Step 1

Sweep the area to be striped.




Step 2

For best results shake can for at least one minute.




Step 3

Insert can *firmly* into Super Stripper. The new spade tip self-orientates regardless of how you place the can, to give you solid stripes every time!




STRIPE WIDTH & LENGTH



Step 4


Place paper below Super Stripper®. Using the VIEWING WINDOW and HEIGHT ADJUSTMENT GAUGE on the side of the handle as a guide, adjust handle **up** for a wider stripe or **down** for a narrower stripe. Secure PINCH LOCK in place by pushing it down onto HANDLE. You are now ready to stripe!



When striping, watch SPEED INDICATOR READINGS for proper & consistent stripes.

STOPPED POSITION

Dot Pattern A



SPEED FOR NEW STRIPING

Dot Pattern B



Look at dot pattern B only. Stripe at the speed where dots have just begun to form a solid line.

SPEED FOR RESTRIPIING

Dot Pattern A



Look at dot pattern A only. Stripe at the speed where dots have just begun to form a solid line.